MATERIAL SAFETY DATA SHEET

LaMOTTE COMPANY
PO BOX 329 - CHESTERTOWN - MARYLAND - 21620
TELEPHONE # FOR INFORMATION 410-778-3100

24 Hour Emergency Number (CHEM-TEL) 800-255-3924

1. PRODUCT IDENTIFICATION

Sulfuric Acid, 0.12N *Code Nr.* **7748**

2. HAZARDOUS INGREDIENTS

NAME	CAS #	TSCA #	%	PEL	TLV
^ Sulfuric Acid	7664-93-9		0.6	1 mg/cubic m	1 mg/cubic m

3. NON-HAZARDOUS INGREDIENTS EXCEPT WATER (7732-18-5)

NAME	CAS #	%
Water to 100%		

4. PHYSICAL DATA

Appearance: Clear Colorless Liquid

Solubility in Water: Soluble	*Odor:* None	*Boiling Point:* ca. 100 degC	*Melt. Point:* N/A
Vapor Pressure: <17 @ 20 deg C	*Vapor Density:* <1 (Air=1)	*pH:* 1	

5. FIRE AND EXPLOSION DATA

Flash Point (method used) N/A | *Flammable Limit: LEL:* N/A | *UEL:* N/A

Extinguishing Media: Not a fire hazard

HMIS Hazard: Health - 1 *Flammability -* 0 *Reactivity -* 0 *Scale: 4 = Extreme, 3 = High, 2 = Moderate, 1 = Slight, 0 = Least*

Special Fire Fighting Procedures:
N/A

Unusual Fire & Explosion Hazard:
N/A

6. REACTIVITY DATA

Stability:
☒ *Stable*
☐ *Unstable*

Conditions to avoid: N/A

Incompatibility (Materials to avoid):
N/A

Hazardous Decomposition Products: SOx

7. HEALTH HAZARD DATA

Toxicity: orl rat LD50: 2140 mg/kg for sulfuric acid, concentrated

Primary Route of Entry: ☐ *Inhalation* ☒ *Skin* ☒ *Ingestion* ☐ *N/A*

Carcinogenicity: ☒ *None* ☐ *NTP* ☐ *OSHA* ☐ *IARC*

Other Health Related Comments:

Target Organs: N/A

Signs and symptoms of exposure:
May be irritating to skin. May be harmful if swallowed.

Medical Condition Aggravated by Exposure: N/A

8. EMERGENCY FIRST AID PROCEDURES

Eye Contact: Flush thoroughly with water for 15 minutes. Consult a physician.

Ingestion: Rinse mouth. Drink glass of water. Consult physician.

Inhalation:
N/A

Skin Contact:
Flush with water. Remove affected clothing and wash skin with soap and water.

9. SPILL AND DISPOSAL PROCEDURES

Spill and Leak:
Cover spill with sodium bicarbonate. Scoop up slurry and wash down drain with excess water.

Disposal:
Add slowly to a solution of soda ash and slaked lime. Pour neutralized solution down drain with excess water. Dispose according to federal, state and local regulations.

10. PRECAUTIONARY MEASURES

In Handling: ☒ *Gloves* ☒ *Eye Protection* ☐ *N/A* ☒ *Other:* Lab Coat

Ventilation ☒ *Normal* ☐ *Mechanical* ☐ *Respiratory Protection*

Work/Hygienic Practices: Avoid contact with skin and clothing.

11. SPECIAL PRECAUTIONS

N/A

DATE: 5/4/03

The above information is believed to be correct but does not claim to be all inclusive and should be used only as a guide.

^ This is a toxic chemical subject to reporting requirements of section 313 of EPCRA and 40CFR372.